




V6 Vacuum Line Routing



Metal Vacuum Line Set

Replacing the factory plastic lines can solve many idle and running issues with the V6 engine. The plastic lines tend to get brittle with age which can cause vacuum leaks. These leaks can cause idle fluctuation, stumbling and poor fuel economy. The Fiero Store's metal vacuum line set will solve these issues and still look like factory originals.

Must re-use factory rubber fittings.  
To make fitting installation easier,  
apply a little lubricant to the end of  
each line, before pushing the rubber  
fittings in place.

Rear most port on  
throttle body to bottom  
port on EGR solenoid

EGR Valve to top port  
on EGR solenoid

MAP sensor "T"

Forward side of throttle  
body to trunk wall

Trunk wall to left  
side of intake

Fuel Regulator to  
MAP sensor

PCV Valve

